
Winstar Display Co., LTD
華凌光電股份有限公司

EVAL_KIT_WO240128B

LCD COG 240x128



Kit Assembling Guide:

1) Connect the LCD FPC (1) to ZIF connector (2) of the first board
2) Connect Anode wire (3) and Cathode wire (4) to the Anode and Cathode wires of the second board: Power supply 3.3V
3) Connect Anode (5) and Cathode (6) wires to the A (7) and K (8) pins of the display: Power supply 3.5V

The demo shows different types of pages that scroll automatically

Represented by:
first FC components
FIRST Components s.r.l.
www.first-components.com
technical@first-components.com
+39 0332 1888005