



WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan

TEL/+886-4-2568 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

Notification Subject: PCN for the driver IC in WF096-80160F and WF18-128160F/G/H series

■ Issue Date : 2026 / 07 / 06

NO.: PCN20260706

■ Description: Winstar's WF096-80160F and WF18-128160F/G/H series will be PCN due to the Driver IC ST7735S-G4-1 EOL issue. The original manufacturer is adjusting wafer capacity allocation and will be end of this IC model in Sep. We expect to inform you the comparison reports soon after testing the new alternative IC ST7735P3-G6-1S. Thank you for your understanding and consideration.
Pls. refer to attachments for further details.

■ Appearance Difference : [NO](#)

■ Electrical Difference : [TBC](#)

■ FW Difference: [TBC](#)

■ Last Buy Date: [Aug. 31, 2026](#)

■ Last Shipment: [May 14, 2027](#)

Item	Before Change	After Change
Part no.	《Standard series》 WF096-80160F 、 WF18-128160F/G/H 《Customized series》 WJ0096A 、 WJ0096A1 、 WJ0096B 、 WJ0096C 、 WJ0096D 、 WJ0096E 、 WJ0096F 、 WJ0096G 、 WJ0096J 、 WJ0096L 、 WJ0096M 、 WJ0096N 、 WJ0096P 、 WJ18E 、 WJ18F 、 WJ18G 、 WJ18H 、 WJ18J 、 WJ18L 、 WJN0180A3	the same

WINSTAR appreciated your support in our products and we will continue to do our best to support and work with you. If there have any further questions, please do not hesitate to reach out to your dedicated sales service representative. Thank you!

Best regards,

Candice Wang